Oil Field Environmental Incident Summary

Responsible Party: zargon oil nd inc

Well Operator: ZARGON OIL (ND) INC.

Well Name: H. BERGSTROM 3

Field Name: HAAS Well File #: 6983

Date Incident: 7/14/2014 Time Incident: 09:00 Facility ID Number:

County: BOTTINEAU Twp: 163 Rng: 83 Sec: 23 Qtr: NE SW

Location Description: h bergstrom #3

Submitted By: rodger hanson Received By:

Contact Person: Daryl Harrison

700 333 5TH AVE SW CALGARY, AB T2P 3B6

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No Reported to NRC: Yes

	Spilled	Units	Recovered	Units
Oil	3	Gallons	3	Gallons
Brine	3	Barrels	3	Barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

low

Areal Extent:

from unit to edge of lease and 6 foot wide by 30 foot long in field

Followup

Units

Potential Environmental Impacts:

getting salt water on ground.

Action Taken or Planned:

we got a payloader and a skidsteer and picked up all contaminated soil and put in container to be hauled to a landfill. then I changed the bad nipple and started the well. then I ordered a load of black dirt to replace the dirt we took out of the field.

Wastes Disposal Location: authorized land fill

Agencies Involved:

Updates

Date: 7/17/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from an on-location valve/piping leak flowed off the location into a cultivated field according to the report. Followup is necessary to confirm adequate cleanup and restoration of the off-site impacts.

Date: 7/17/2014 Status: Inspection Author: Washek, Sandi

Updated Oil Volume: 3.00 gallons

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 11:59am. The weather was sunny; hot wind out of the SW at 5 mph. The site had already been cleaned up on arrival. Company rep informed me that the landowner was ok with the cleanup. The site was about 30 ft x 10 ft in size. The soil had been removed and sent to PDI in Tioga. New clean topsoil was brought in and leveled out. There was no impact to water. No additional followup needed.